

Marine Software RELEASE NOTES

(Controller series) Version 5.5.2R (26/10/2022)

*****See important compatibility notice below for old BBFF Black Box not-Chirp Fish Finder*****

IMPORTANT: This version is compatible ONLY with Controllers with Unit ID 1007

Bug Fixed:

- Device does not reboot anymore when left in operation continuously for a couple of days

***** Compatibility Notice:**

- **WARNING: Marine Software Family 5.x (including all versions starting from release 5.0.0R), is NOT compatible with any legacy NON-Chirp FishFinders (FFs). Therefore:**
 - **DO NOT UPDATE YOUR SW IF...** you must use any NON-Chirp FF with your navigation system. Such NON-Chirp FFs are only compatible with Marine SW 4.2.0R (and earlier versions);
 - **YOU MUST UPDATE YOUR SW IF...** you will use a new Black box Fish Finder with Chirp technology (BBFF-Chirp). The new BBFF-Chirp is only compatible with Marine SW 5.0.0R (and later versions). Remember that any existing CW transducer that you have installed and used with a legacy NON-Chirp FF can also be used with a new BBFF-Chirp, although the BBFF-Chirp will function in CW mode unless it is connected to a Chirp transducer.

For additional information please contact AvMap.